


WEEKLY RIG REPORT
OCS-G-8718, WELL NO. 1
SOUTH TIMBALIER BLOCK 47



<u>01/06/88</u>	DEPTH TO DATE: 14475	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/05/88: TD 14,475' MW 10.8# FWH to 14,380'. Ramed to 14,419'. Drd to 14,438'. Pumped slug & FWH. PU BHA & WIH to 2000'. Repair rotary torque sensor. FIH. Drd to 14,475'.		
<u>01/07/88</u>	DEPTH TO DATE: 14640	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/06/88: TD 14,640' MW 10.8# Drd to 14,577'. 1G std short trip. Drd to 14,640'.		
<u>01/08/88</u>	DEPTH TO DATE: 14797	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/07/88: TD 14,797' MW 10.8# Drd to 14,706'. Md 20 std wiper trip. Drd to 14,797'.		
<u>01/09/88</u>	DEPTH TO DATE: 14856	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/08/88: TD 14,856' MW 10.8# Drd to 14,856'. TD for BHA change. GIH.		
<u>01/10/88</u>	DEPTH TO DATE: 15023	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/09/88: TD 15,023' MW 10.6# TIH. Drd to 14,974'. Serv mud. Drd to 15,023'.		
<u>01/11/88</u>	DEPTH TO DATE: 15200	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/10/88: TD 15,200' MW 10.8# Drd to 15,099'. Wiper trip to 9985'. Drd to 15,200'.		
<u>01/12/88</u>	DEPTH TO DATE: 15392	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/11/88: TD 15,392' MW 10.8# Drd to 15,282'. Wiper trip to 9981'. Drd to 15,392'.		
<u>01/13/88</u>	DEPTH TO DATE: 15451	8/8 EST BCP COST
		8/8 EST ACP COST
		8/8 TOT EST COST
01/12/88: TD 15,451' MW 10.8# Drd to 15,451'. POOH. Tstd BOPs. GIH.		

BEST AVAILABLE COPY